


# BULK PACKAGING RECOMMENDATIONS

## Part Protection In-Process


To stop corrosion before it starts, place ARMOR Poly® VCI Bags or Film or lay ARMOR Wrap® VCI Paper over parts while parts are not being worked on.

**IDEAL FOR:** any metal in process

ARMOR POLY® VCI Bag  
(over top)



ARMOR WRAP® VCI Paper  
(over top)



Please note that these recommendations are based upon "Best Practices" developed by ARMOR Protective Packaging® professionals in conjunction with our customers. Since every situation is different, ARMOR recommends conducting a "real life" test shipment for best results.

